Report on visit to four proposed sites in Ciudad Juarez

Summary: Members of the administrative unit of the air quality monitoring fund (Ricardo Aragon, Cesar Fierro and Sergio Vasquez), the Mexican co-president (Ing. Oscar Fentanes), and researchers from the Autonomous University of Ciudad Juarez (UACJ) visited four proposed sites on March 23, 2022 for the installation of a new air quality monitoring station in Ciudad Juarez.

The sites were first categorized by their location with respect to the current urban growth, population density and availability of services (electricity, security, internet, etc.)

The proposed sites in the order they were visited:

- 1. JMAS ANAPRA
- 2. Fire station Anapra (Bomberos Anapra)
- 3. Nutrition Clinic (Clínica de Nutrición)
- 4. UACJ Community Center (Centro Communitario)

Based on the findings on the visit and a follow up meeting, the attendees discussed the advantages and disadvantages of each of the visited sites and the administrative unit recommends that the site "Nutrition Clinic (Clinica de Nutricion)" is the best option to install a new air monitoring station. This recommendation was determined due to the location of the station, which is inside south urban region of the city. It is important to highlight that there currently is no active air quality monitoring in this part of the city and that the closest air monitoring station is approximately 3.5 miles away. In addition, the site is located in a part of the city where there is a projected higher growth rate in terms of population with new neighborhoods projected in the coming years. The site is located within the facilities of the Nutrition Clinic of the UACJ, and has security, electricity, and other services. Finally, this site is being contemplated to install a Ceilometer and other atmospheric and climatic characterization equipment by the UACJ; Therefore, there is a probability that in the future there will be robust information that will serve for decision-making and the implementation of effective public policies by local government.

Site 1 – JMAS ANAPRA

Name: Planta Tratadora de Aguas Residuales JMAS Anapra

Address: C. Congrio s/n Esq. C. Delfín, Rancho de Anapra, 32107 Cd Juárez, Chih, México.

Google Maps:

https://www.google.com/maps/place/Planta+Tratadora+De+Aguas+Rediduales+JMAS+Anapara/@31.7829703,-

106.5704553,1170m/data=!3m1!1e3!4m5!3m4!1s0x0:0xb8cd74564995f5ef!8m2!3d31.782590 7!4d-106.5746764

Wind Direction: The prevailing winds in spring come from the west, in summer from the east, in the autumn from the north-east and in the winter from the southwest. During the Winter the wind direction is in the direction of Mexico-USA border.

Growth: The city has not contemplated new growth or new neighborhoods in Anapra.

Distance to other air monitoring stations: The closest air monitoring station to JMAS Anapra in Ciudad Juarez is Canales Lira. Canales Lira is located 7.6 miles in a straight line from JMAS ANAPRA. (See Attachment A for an accurate map)

Estimated population or neighborhood to be benefited with a station in this location: **The** neighborhoods of Lomas de Poleo, Rancho de Anapra (Anapra Ranch) and Puerto de Anapra (port of Anapra)

Advantages	Disadvantages
1. The site has electricity	1. Entrance of the site is difficult to
2. There is security 24/7 (see Picture 3 for fence)	access because there is no formal urban development, roads are not
3. Near the border and the	paved.
measurements could complement the measurements made by stations on	Urban growth in the area is very limited.
the US side of the border.	Site is isolated and the roads are not paved.
	 It is not a good site for a new air quality monitoring station since it is not representative of Ciudad Juarez and the population density in the area is low.



Picture 1 - Location JMAS ANAPRA



Picture 2 - Satellite view of JMAS ANAPRA



Picture 3 – Entrance to JMAS ANAPRA.



Picture 4 - Entrance to the site, there is security 24/7



Picture 5 – There is not much around the site

Site 2 – Fire Station 9 – ANAPRA (Estación de Bomberos)

Name: Fire Station 9 - Anapra (Estacion de Bomberos - ANAPRA)

Address: C. Esturión s/n Esq. C. Raya, Puerto de Anapra, 32107 Cd Juárez, Chih, México.

Google Maps:

https://www.google.com/maps/place/Estaci%C3%B3n+de+Bomberos+9/@31.7742891,-106.5606226,16.35z/data=!4m5!3m4!1s0x0:0x4e36b16ae42d7be7!8m2!3d31.773527!4d-106.5613873

Wind Direction: Due to its geographical location, the prevailing winds in spring come from the west, in the summer from the east, in autumn from the north-east and in winter from the southwest (season of the year in which air transport is in the direction of the Mexico-US border)

Growth: The growth of the city has not contemplated new growth in Anapra.

Distance to other air monitoring stations: The nearest station is Canales Lira, approximately 6.6 miles in a straight line.

Estimated population or neighborhood to be benefited with a station in this location: The benefited neighborhoods of having a monitoring station in this area are Lomas de Poleo, Rancho Anapra y Puerto Anapra.

Advantages		Disadvantages	
1.	Site has electricity	1.	It may be more expensive to install
2.	There are several options on where		station on top of fire station.
	the station can be placed. One option	2.	It is required to install an electrical
	is above the fire station (must confirm		connection of approximately 100m/
	the structure of the building, see		109 yards to provide electricity to
	picture 9) and the other is in the		station.
	corner of the property (see Picture	3.	We must install the modem and
	10)		contract the service to be able to
			have internet connection at the
			station.
		4.	If station is placed at ground level, we
			must build a concrete slab to level the
			floor.
		5.	Current equipment on site has been
			stolen and site has been vandalized.
			Security is not very secure.
		6.	Limited growth



Picture 6 - Location



Picture 7 - Satellite view of Fire Station - Anapra



Picture 8 – Closer view of fire station location



Picture 9 – Fire Station, site can be placed on top



Picture 10 – Monitoring station can be placed on the corner of the site.

Site 3 – Nutrition Clinic (Clínica de Nutrición) (Recommended Site)

Name: Nutrition Clinic (Clinica de Nutricion)

Address: C. Batalla de Zacatecas y Esq. C. batalla de Sta. Rosa, Enríquez Guzmán, 32675 Cd Juárez, Chih., México.

Google Maps:

https://www.google.com/maps/place/Centro+Comunitario+Nutricional+de+La+UACJ/@31.655 7901,-106.4670425,1303m/data=!3m1!1e3!4m9!1m2!2m1!1sClinica+de+nutricion+-+UACJ!3m5!1s0x86e75e3e44d556ef:0xf5d464640aa1a37a!8m2!3d31.6552216!4d-106.4662969!15sChtDbGluaWNhIGRIIG51dHJpY2lvbiAtIFVBQ0oiA4gBAZIBEGNvcnBvcmF0ZV9vZ mZpY2U

Wind Direction: The prevailing winds in spring come from the west, in summer from the east, in autumn from the north-east and in winter from the southwest.

Growth: The growth of the city has not contemplated new growth.

Distance to other air monitoring stations: **Closest monitoring station is Advance**, **approximately 3.6 miles in a straight line**.

Estimated population or neighborhood to be benefited with a station in this location: **The** benefited neighborhoods of having a monitoring station in this area are Enríquez Guzmán, Toribio Ortega, Colinas del Sur, Cementera y Pradera de los Oasis II.

Advantages	Disadvantages
 Site includes all services (UACJ 	1. Will have to build a concrete slab
infrastructure, electricity, internet,	2. Street is no paved, it can impact
and security)	PM10 measurements.
2. It is in an area with a higher	
population density compared to the	
two previous proposals and the city	
maintains urban development in this	
part of the city.	
3. It can become an operational center	
with various monitoring equipment.	
UACJ will install their ceilometer at	
this site and there is a meteorological	
tower currently at the site.	
4. Area is marginalized and there is no	
air quality index in the area. New	
station at this location will provide	
actual air quality data for a part of a	
city that does not have air quality	
measurements.	
5. Closest stations is advance and is 20	
minutes award by car (3.5 miles in a	
straight line).	
6. Location has a high population	
density.	



Picture 11 - Location



Picture 12 – Satellite view of the Nutrition Clinic



Picture 13 – Close aerial view of the site



Picture 14 – Nutrition Clinic and a meteorological tower installed at site



Picture 15 – Monitoring Equipment at site

Sitio 4 – Community Center (Centro Comunitario)

Name: Community Center (Centro Comunitario – UACJ)

Address: C. Tierra de Fuego 1519 Esq. Av. Lote Bravo Cerradas del Sur, 32590 Cd Juárez, Chih, México.

Google Maps:

https://www.google.com/maps/place/Centro+Comunitario+-+UACJ/@31.585674,-106.4058719,13.19z/data=!4m5!3m4!1s0x0:0x44f408975cebcc14!8m2!3d31.5774697!4d-106.3724526

Wind Direction: The prevailing winds in spring come from the west, in the summer from the east, in autumn from the north-east and in the winter from the southwest.

Growth: The city does have contemplated new neighborhoods and growth in this area.

Distance to other air monitoring stations: The closest air monitoring station is Advance and is approximately 9 miles in a straight line.

Estimated population or neighborhood to be benefited with a station in this location: **The** benefited neighborhoods of having a monitoring station in this area are Cerradas del Sur, Parajes del Sur, Arecas, La Enramada, Enramada I y II.

Advantages		Disadvantages	
1.	Greater growth in the future	1.	Few public vehicles, most vehicles are
2.	Industrial zone		private (18 wheelers).
3.	There are no monitoring stations in	2.	Will have to install a concrete slab
	this area		and protective mesh around the site.
4.	Will be located in a community	3.	Low population density due to being
	center, which can in turn give real air		located in the industrial zone.
	data quality to the community	4.	Not representative of the air quality
5.	Includes Electricity and Internet.		of Ciudad Juarez and could be a
			transport station for pollutants or a
			baseline for this region.



Picture 16 - Location



Picture 17 – Satellite view of the Community Center



Picture 18 – Close aerial view of the community center



Picture 19 – Community Center



Picture 20 – Fence, left side of community center



